




$$\text{slope} = \frac{\Delta y}{\Delta x} = \frac{800 - 600}{6 - 4} = 100$$

C

$$L = 14 \text{ m}$$

$$F = 15 \text{ kN}$$

$$EI = 20 \text{ MNm}^2$$

1) Max deflection

$$= \frac{1}{2} (15 \text{ kN} \times 14 \text{ m})$$

$$= 105 \text{ kNm}$$

$$= \frac{105 \times 10^3}{20 \times 10^6}$$

$$= \frac{WL^3}{3EI} = \frac{15 \times 10^3 \times 14^3}{3 \times 20 \times 10^6}$$

$$= 0.686 \text{ m}$$

11) Slope of the beam

$$W = mg$$

$$\frac{1}{R} = \frac{M}{EI} = \frac{d^2 y}{dx^2}$$

$$m = \frac{15000}{9.81}$$

$$= 1529.051$$

$$= \frac{1529.051}{20 \times 10^6}$$

$$\frac{1}{R} = 3.058102 \times 10^{-5}$$

$$R = 3.27 \times 10^4$$

Radius of curvature

600
800
1000
1200

0.0071
0.00592
0.0082
0.01

From graph.

$$1) K = \sqrt{\frac{\text{slope} \times g r_1^2}{2m}}$$

$$m = \frac{D}{x}$$

$$\text{slope} = 100$$

$$K = \sqrt{\frac{100 \times 9.81 \times 1^2}{9.8174 \times 10^{-4}}} = 9.99$$

$$V = A L$$

$$= \pi r^2$$

$$= \pi \times (0.5)^2 \times 1 \times 2$$

$$= 9.81 \text{ cm}^3$$


$$V = \pi \times 0.125^2 \times 1 \times 0.02$$

$$= 9.8174 \times 10^{-4}$$

$$\text{Theoretical, } K = \frac{R}{\sqrt{2}} = \frac{12.5}{\sqrt{2}} = 8.83$$

$$K = \sqrt{\frac{\text{slope} \times g r_1^2}{2m}}$$

$$K = \sqrt{\frac{I}{M}} = \frac{I}{m} \quad \begin{matrix} I = \text{moment of inertia} \\ m = \text{mass} \end{matrix}$$



Moment of Inertia acting under gravity $I = g r^2$. from graph, slope is $\propto$ proportionality

Q4

415V, 50Hz 6 pole 3 phase Induction motor
slip of 4%

Wattmeter method $\begin{matrix} 65 \text{ kW} \\ 50 \text{ kW} \end{matrix}$

$$s = \frac{N_s - N}{N_s}$$

Delta $\Rightarrow 0.5 \Omega$

stator loss 1.5 kW

Mechanical loss = 2 kW

i) Synchronous speed

$$N_s = \frac{F \times 60}{\text{number of poles}} = \frac{50 \times 120}{6} = 1000 \text{ rev/min}$$

ii) Rotor speed

$$\begin{aligned} n &= n_s \times (1 - s) \\ &= 1000 \times (1 - 0.04) \\ &= 960 \text{ rev/min} \end{aligned}$$

iii) Total input power

$$W = V \times A = 415 \times$$

From ohm's law $V = IR$

$$I = \frac{V}{R} = \frac{415}{0.5} = 830 \text{ A}$$

$$= 415 \times 830 = 344.450 \text{ kW}$$

iv) Line current from supply

$$I_p = \frac{I_L}{\sqrt{3}}$$

$$I_L = \sqrt{3} I_p$$

$$= 830 \sqrt{3} = 1437.60 \text{ A}$$

vi. Stator Copper loss

$$P = 3I^2 R = 3 \times (14376)^2 \times 0.5 \\ = 3100.4 \text{ kW}$$

vii. Air gap power

$$P_{\text{gap}} = \frac{P}{s} = \frac{344.45}{0.04} \\ = 8611.2 \text{ W}$$

viii. Rotor Copper loss

$$s = \frac{\text{Rotor Copper loss}}{\text{Rotor Input}} = s_p \times \text{Air gap}$$

$$\text{Rotor Copper loss} = 0.04 \times 8611.2 \\ = 344.48 \text{ W}$$

ix. Useful power output

$$T = \frac{P}{\omega_n}$$

$$\omega_n = \frac{2\pi N}{60} = \frac{2 \times \pi \times 1000}{60} = 104.72 \text{ rad/s}$$

$$T = \frac{344.45}{104.72} = 3.28 \text{ Nm}$$

$$= 115000 \times 3.28$$

$$= 3695.185 \text{ kW}$$

ii) NH_4Cl and NaCl in H_2O


$$T = \frac{3695.125}{104.72} = 35.30 \times 10^3 \text{ Nm}$$

X1 Machine Efficiency

$$E = \frac{P}{100} \times 100$$

$$\begin{array}{r} 115 \\ \times 100 \\ \hline 3695.12 \\ = 3.1\% \end{array}$$

6



- i) adjusting ohm resistance will cause a faster fall in V_{CE} . P. 11 B.
- ii) Reducing supply voltage. cause the static inq. at point C

Beefsteak

- 1) Allow control of the speed or torque and torque.
- 2) Increase torque of induction motor.


415V 50Hz 8pole star 3phase

$$I_L = 65$$

$$P_f = 0.8$$

$$\text{Synchronous R } 0.75 \Omega$$

1)



(1) Required 1-dred enf.

$$E = V - I_a (r_s + r_a)$$

$$E = \frac{P \phi N \times Z}{60 \text{ A}}$$

$$E = 415 - 200(0.75) = 265V$$

b

415V, 50Hz, 8 pole star conn

iii) Mechanical load angle

$\delta =$ the angle b/w supply voltage and back emf

$$V = 415V$$

$$E_b = 265V$$

$$\Rightarrow 2 \sin^{-1} \left(\frac{265}{415} \right)$$

$$= 39.68^\circ$$

b

$$P = 1.75 MW$$

$$P_f = 0.6$$

$$V = 11kV$$

1)

$$kW = \frac{V \times I \times P_f \times 1.732}{1000}$$


$$= \frac{11 \times 10^3 \times 1.75 \times 10^6 \times 1.732 \times 0.6}{1000}$$

$$= 20004.6 kW$$

$$kVAR \Rightarrow Q = X \cdot I^2$$

$$\varphi = \sin^{-1} \frac{kVA}{kW}$$

$$\sin \theta =$$



$$\pm (20004.6 \times 0.6) = \underline{\underline{12002.76}}$$

$$\text{line current} = \frac{VA}{Y} = \frac{1.75 \times 10^6}{1.1 \times 10^3}$$

$$= 159.09 A$$

iii) VAR

$$P = 500 \text{ kW}$$

$$\text{efficiency} = 80\%$$

$$\text{P.f} = 0.9 \text{ lag}$$

$$P = VA \times \text{P.f.}$$

$$\frac{\text{apparent power}}{\text{real power}} = \text{P.f.}$$

$$\text{Apparent power} = \frac{500 \text{ kW}}{0.9} = 555.5 \text{ kW}$$

$$\text{load power factor, } \cos \theta = 0.9 = 25.84^\circ$$

$$\text{motor power} = 500 \text{ kW}$$

$$\text{Overall power factor} = \cos \alpha = 0.9 \text{ lag}$$

$$\text{Apparent power} = \frac{500}{0.9} = 555.5 \text{ kW}$$

$$\text{Motor P.F.} = \frac{25.84}{555.5} \times 415 = \underline{\underline{0.75}}$$

~~Example 1~~

$$Q_s \quad I = 2.5 \text{ A} \quad R = 25 \Omega$$

800000

$$W = 2774 = \frac{28 \times 10^3 \times 850}{60}$$

$$= 89.018 \text{ m/s}$$

~~Power~~

$$V I_a = I_a^2 R_a$$

$$\begin{aligned} \text{Input power} &= 117 \\ &= 1851250 \\ &= 31.250 \text{ kW} \end{aligned}$$

$$P_{\text{out}} = T \omega$$

shaft torque

$$\text{sh } T = P = \frac{31.250 \times 10^3}{89.018} = 351.097 \text{ Nm}$$

$$P_{\text{out}} = E_b I_a - I_a^2 R_a$$

$$E_b = V - I_a (0.25) = 218.75 \times 89.018$$

$$= 250 - 125 (0.25) = 218.75 \text{ kW} + 185000$$

$$= 19469.14 \text{ W}$$

$$\text{efficiency} = \frac{P_{\text{out}}}{P_{\text{in}}} = \frac{19489.19}{31250} = 62.37\%$$

$$b) I_a = 200A$$

$$\begin{aligned} E_b &= V - I_a (R) \\ &= 250 - 200(0.25) \\ &= 200V \end{aligned}$$

$$E = \frac{P \phi N \times 2}{60 A}$$

$$\phi = \frac{200}{31250} = 6.4 \times 10^{-5} \text{ Wb}$$

$$P = 1500W$$

$$200 = \frac{1500 \times 3125 \times \phi}{60}$$